

Late changes after printing of Final Program



12th ECNDT
GOTHENBURG-SWEDEN-2018

Day	Room	Time	Session	Title	Change	New position in the program			
Day	Room	Time	Session	Title	Change	Day	Room	Time	Session
Tuesday	H1	09:00	Additive Manufacturing – ultrasound	Ultrasonic inspection ...	Withdrawn				
Tuesday	G3	09:20	X-ray radiography 3	Multiclass ...	Withdrawn				
Tuesday	H2	11:10	Oil & Gas 4	Profiling device ...	Withdrawn				
Tuesday	G2	11:50	Nonlinear Ultrasonics 1	Triaging and ...	Withdrawn				
Wednesday	H1	11:30	Structural Health Monitoring 4	Quantified Visual ...	Withdrawn				
Thursday	R2	10:50	Surface Methods 2	Combination of ...	Poster 52				
Thursday	G2	16:00	Applied PAUT 2	Automated	Withdrawn				
Monday	H2	16:00	Oil & Gas 2	In-service ...	Moved	Thursday	G2	16:00	Applied PAUT 2
Tuesday	G3	09:40	X-ray radiography 3	Plastic ...	Moved	Tuesday	G3	09:20	X-ray radiography 3
Tuesday	G3	10:00	X-ray radiography 3	Dimensional ...	Moved	Tuesday	G3	09:40	X-ray radiography 3
Tuesday	H2	11:30	Oil & Gas 4	Improvement the ...	Moved	Tuesday	H2	11:10	Oil & Gas 4
Tuesday	H2	11:50	Oil & Gas 4	Development of ...	Moved	Tuesday	H2	11:30	Oil & Gas 4
Wednesday	G1	15:40	Materials Characterization UT	Stress measurement ...	Moved	Wednesday	G1	16:40	Materials Characterization UT
Wednesday	G1	16:40	Materials Characterization UT	Development of ...	Moved	Wednesday	G1	15:40	Materials Characterization UT
Thursday	R2	11:10	Surface Methods 2	Laser Speckle ...	Moved	Thursday	R2	10:50	Surface Methods 2
Thursday	R2	11:30	Surface Methods 2	Development of ...	Moved	Thursday	R2	11:10	Surface Methods 2
Thursday	H1	15:40	Thermography and Thermosonics App.	Alternative to ...	Moved	Thursday	H1	14:10	Thermography and Thermosonics 3
Thursday	H1	16:00	Thermography and Thermosonics App.	Processing infrared ...	Moved	Thursday	H1	15:40	Thermography and Thermosonics App.
Thursday	H1	16:20	Thermography and Thermosonics App.	Defect Analysis ...	Moved	Thursday	H1	16:00	Thermography and Thermosonics App.
Friday	G2	10:50	Data Processing - UT	Signal Processing ...	Moved	Tuesday	H1	10:00	Additive Manufacturing - Ultrasound
Friday	R2	10:50	Visual Techniques	Performance ...	Moved	Thursday	R2	11:30	Surface Methods 2
Friday	R2	11:10	Visual Techniques	Improvements in ...	Moved	Friday	R2	10:50	Visual Techniques
Friday	R2	11:30	Visual Techniques	Condition monitoring ...	Moved	Friday	R2	11:10	Visual Techniques
Friday	R2	11:50	Visual Techniques	The Challenge ...	Moved	Friday	R2	11:30	Visual Techniques